DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000063 Address: 333 Burma Road **Date Inspected:** 19-Jan-2007

City: Oakland, CA 94607

OSM Arrival Time: 800 **Project Name:** SAS Superstructure **OSM Departure Time:** 1700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Huang Wei No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Bid 52, 55 Tower and Girder

Summary of Items Observed:

Office of Structural Materials Quality Assurance Inspector (QA), Mark Wright was present as requested to observe quality control functions related to procedure qualification record (PQR) testing at the ZPMC facility in Shanghai, China for the San Francisco Oakland Bay Self Anchored Suspension Bridge.

The Caltrans Quality Assurance (QA) Inspector was present as requested to witness the mechanical testing of HP2006129 and HP2006131 Procedure Qualification (PQR) test plates. The QA Inspector observed tensile test on reduced sections and all weld metal specimens along with side bends, Charpy Vee Notch (CVN) and macro etch test. The test was performed per the AWS D1.5, Section 5.18 requirements. The test appeared to comply with the contract documents with the exception of HP2006131due to the Charpy Vee Notch (CVN) impacts were low. The ZPMC lab personnel stated that the samples would be removed from another part of the plate and the CVN test would be performed tomorrow. Lot numbers issued were B41-021-07 and B41-022-07.

Summary of Conversations:

See Task Leader journal for this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By: Wright, Mark Quality Assurance Inspector

Reviewed By: McClary,David QA Reviewer